

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: OCTOBER 2006

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "CI-208-020320")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "PE-214-020320")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)

CP (Complaint)

MD (Manufacturer Defect)

ID (Part 574)

MI (Manufacturer Inquiry)

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
27	202	Head Restraints	Vehicle-15	TEST
28	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
29	204	Steering Control Rearward Displacement	Vehicle-17	TEST
30	205	Glazing Materials (Inspection)	Equipment	Insp.-6
31	206	Door Locks & Door Retention Components	Equip.-8	TEST
32	207	Seating Systems	Vehicle-18	TEST
33	208	Occupant Crash Protection	Vehicle-19	TEST
34	209	Seat Belt Assemblies	Equip.-9	TEST

35	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
36	212	Windshield Mounting	Vehicle-21	TEST
37	213	Child Restraint Systems	Equip.-10	TEST
38	214	Side Impact Protection	Vehicle-22	TEST
39	216	Roof Crush Resistance	Vehicle-23	TEST
40	217	Bus Window Retention & Release	Vehicle-24	TEST
41	218	Motorcycle Helmets	Equip.-11	TEST
42	219	Windshield Zone Intrusion	Vehicle-25	TEST
43	220	School Bus Rollover Protection	Vehicle-26	TEST
44	221	School Bus Body Joint Strength	Vehicle-27	TEST
45	222	School Bus Passenger Seating	Vehicle-28	TEST
46	223	Rear Impact Guards	Equip.-12	TEST
47	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
48	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
49	301	Fuel System Integrity	Vehicle-30	TEST
50	302	Flammability of Interior Materials	Equip.-13	TEST
51	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
52	304	CNG Fuel Container Integrity	Equip.-14	TEST
53	305	Electric Vehicles	Vehicle-32	TEST
54	401	Interior truck Release	Vehicle	TEST
55	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 34 vehicle standards, 14 equipment standards, 7 inspection standards				

REPORTS ACCEPTED DURING SEPTEMBER 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
108	CAN 011	DAIMLER/ CHRYSLER	2006 VALEO SYLVANIA CHRYSLER 300 LAMPS/CONSPICUITY SYS.	PASS 638506
108	CAN 012	SUBARU	2006 SAMLIP SUBARU TRIBECA B9 LAMPS/CONSPICUITY SYS.	PASS 638519
108	CAN 013	HONDA	2006 STANLEY HONDA ACCORD LAMPS/CONSPICUITY SYS.	FAIL-P ¹ 638539
108	CAN 014	GENERA	2006 TYC HONDA ACCORD LAMPS/CONSPICUITY SYS.	FAIL-P ² 638540
124	KAR 001	DAIMLER/ CHRYSLER	2006 JEEP WRANGLER MPV 2-DOOR	PASS 638520
124	KAR 003	DAIMLER/ CHRYSLER	2006 DODGE DAKOTA PICKUP TRUCK 4-DOOR	PASS 638542
218	SRI 007	WOMBAT TRADING	2006 M2R MR-11 COMP. FACIAL MOTORCYCLE HELMET	PASS 638530
218	SRI 009	SIXSIXONE	2006 SIXSIXONE FLIGHT COMP. FACIAL MOTORCYCLE HELMET	PASS 638531
218	SRI 014	TONG HO HSING	2006 CYBER HELMETS U-12 FULL MOTORCYCLE HELMET	FAIL-P ³ 638532
218	SRI 015	DAYTONA HELMETS	2006 DAYTONA SKULL CAP PARTIAL MOTORCYCLE HELMET	FAIL-P,L ⁴ 638533
218	SRI 016	TONG HO HSING	2006 SKID LID U-69 PARTIAL MOTORCYCLE HELMET	FAIL-P,L ⁵ 638534
218	SRI 017	NOT PROVIDED	2006 VANCE LEATHER HC2102/200 PARTIAL MOTORCYCLE HELMET	FAIL-PL ⁶ 638535
218	SRI 018	BELL HELMETS	2006 BELL HELMETS ZEPHYR COMP. MOTORCYCLE HELMET	PASS 638536
218	SRI 019	JTECH CORP.	2006 XPEED XF 904 COMP. FACIAL MOTORCYCLE HELMET	PASS 638537
218	SRI 020	ADVANCED CARBON	2006 ACC EXT-002 PARTIAL MOTORCYCLE HELMET	FAIL-P ⁷ 638538
218	UST 011	SHOEI	2006 SHOEI V-MOTO COMP. FACIAL MOTORCYCLE HELMET	PASS 638523
218	UST 012	TROY LEE DESIGN	2006 TROY LEE SPEED EQUIP. COMP. FACIAL MOTORCYCLE HELMET	FAIL-L ⁸ 638524

¹ Under review, Halogen headlamps-photometric test.

² Under review, Halogen headlamps-photometric test.

³ Under review, Single penetration failure.

⁴ Under review, Single retention system separation failure; labeling failures.

⁵ Under review, Multiple impact attenuation peak g failures; labeling failures.

⁶ Under review, Single retention system separation failure; labeling failures.

⁷ Under review, Multiple impact attenuation peak g failures; multiple penetration failures

⁸ Under review, Labeling failure.

REPORTS ACCEPTED DURING SEPTEMBER 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
218	UST 017	KBC	2006 KBC HELMET TK-8 COMP. FACIAL MOTORCYCLE HELMET	PASS 638525
218	UST 018	HD POWERSPORTS	2006 NITRO NT100 FULL MOTORCYCLE HELMET	FAIL-P,L ⁹ 638526
218	UST 019	QUEEN KWAN	2006 MOSSI A-633 COMP. FACIAL MOTORCYCLE HELMET	FAIL-L ¹⁰ 638527
218	UST 013	NEXL SPORTS	2006 NXT 05 PARTIAL MOTORCYCLE HELMET	PASS 638496
218	UST 015	HELMET CITY	2006 HCI 100 PARTIAL MOTORCYCLE HELMET	PASS 638497
218	UST 016	MHR	2006 ZOX HELMETS ALTO PARTIAL MOTORCYCLE HELMET	PASS 638507

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L – LABELING

⁹ Under review, Multiple penetration failures; Labeling failures

¹⁰ Under review, Labeling failures

TIRE REPORTS ACCEPTED DURING SEPTEMBER 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFG/ DISTRIB	MY BRAND/ TIRE_NAME/ID NUMBER	HSNO/ RESULT
575	UTG 045	MICHELIN NORTH AMERICA, INC.	2006 MICHELIN PILOT SPORT A/S 4M3VC5JX3505	PASS 6277119
575	UTG 046	MICHELIN NORTH AMERICA, INC.	2006 MICHELIN PILOT SPORT A/S 4M3VC5JX3505	PASS 6277120
575	UTG 070	KELLY-SPRINGFIELD TIRE CO.	2006 KELLY-SPRINGFIELD CUSTOM 428 ALL SEASON PJHLEHLR3205	PASS 6277121
575	UTG 069	KELLY-SPRINGFIELD TIRE CO.	2006 KELLY-SPRINGFIELD CUSTOM 428 ALL SEASON PJHLEHLR3205	PASS 6277122
575	UTG 066	HANKOOK TIRE CO. LTD.	2006 HANKOOK RADIAL H714 1GBMAPH2005	PASS 6277123
575	UTG 065	HANKOOK TIRE CO. LTD.	2006 HANKOOK RADIAL H714 1GBMAPH2005	PASS 6277124
575	UTG 062	UNIROYAL GOODRICH TIRE CO.	2006 UNIROYAL TIGER PAW FREEDOM BHX0BL1U3105	PASS 6277125
575	UTG 061	UNIROYAL GOODRICH TIRE CO.	2006 UNIROYAL TIGER PAW FREEDOM BHX0BL1U3005	PASS 6277126
575	UTG 058	GOODYEAR TIRE & RUBBER CO.	2006 GOODYEAR WINSTON CLASSIC MDX028LR3205	PASS 6277127
575	UTG 057	GOODYEAR TIRE & RUBBER CO.	2006 GOODYEAR WINSTON CLASSIC MDX028LR3205	PASS 6277128
575	UTG 178	NANKUNG RUBBER TIRE CORP.	2006 NANKUNG S-665 SONAR WE9L1680805	PASS 6277388
575	UTG 173	MICHELIN NORTH AMERICA, INC.	2006 MICHELIN HARMONY B93VEUMX3005	PASS 6277389
575	UTG 174	MICHELIN NORTH AMERICA, INC.	2006 MICHELIN HARMONY B93VEUMX3005	PASS 6277390
119	STL 001	SHANGHAI	2006 SHANGHAI RR150 DOUBLE COIN 2J3THR11505	PASS 6277357
119	STL 003	CHAOYANG	2006 CHAOYANG LM518 LONG MARCH 1R3TLM122205	PASS 6277358
119	STL 004	JIANGSU	2006 JIANGSU RADIAL F80 HANKOOK BJ3TM8H0405	PASS 6277359
119	STL 005	MT. VERNON	2006 MT. VERNON M127 TOYO 3CTIMD2105	PASS 6277360
119	UTG 161	BRIDGESTONE/ FIRESTONE	2006 BRIDGESTONE/FIRESTONE WIDETRACK BAJA HT W271WHC3005	PASS 6277361
119	UTG 162	BRIDGESTONE/ FIRESTONE	2006 BRIDGESTONE/FIRESTONE WIDETRACK BAJA HT W271WHC3005	PASS 6277362
119	UTG 157	BRIDGESTONE/ FIRESTONE	2006 BRIDGESTONE/FIRESTONE GILLETTE ACCELERATOR G/T HYM1CL22205	PASS 6277363
119	UTG 158	BRIDGESTONE/ FIRESTONE	2006 BRIDGESTONE/FIRESTONE GILLETTE ACCELERATOR G/T HYM1CL22205	PASS 6277364
119	UTG 165	KELLY-SPRINGFIELD TIRE CO.	2006 KELLY-SPRINGFIELD GRAND SPIRIT TOURING VR PJ654FLR2205	PASS 6277365
119	UTG 166	KELLY-SPRINGFIELD TIRE CO.	2006 KELLY-SPRINGFIELD GRAND SPIRIT TOURING VR PJ654FLR2205	PASS 6277366

TIRE REPORTS ACCEPTED DURING SEPTEMBER 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFG/ DISTRIB	MY BRAND/ TIRE NAME/ID NUMBER	HSNO/ RESULT
119	UTG 169	HANKOOK TIRE CO. LTD.	2006 HANKOOK NATIONAL XT 3000 1GC3B9P1005	PASS 6277367
119	UTG 170	HANKOOK TIRE CO. LTD.	2006 HANKOOK NATIONAL XT 3000 1GC3B9P4804	PASS 6277368
119	STL 006	TRIANGLE	2006 TRIANGLE TR686 TRIANGLE 0HTF1405	PASS 6277369
119	STL 007	CHAOYANG	2006 CHAOYANG LM216 LONG MARCH 1R2JALM10805	PASS 6277371
119	STL 008	MT. VERNON	2006 MT.VERNON M147 TOYO 3C4F1L72805	PASS 6277372
119	STL 009	MT.VERNON	2006 MT.VERNON M627 TOYO 3C4F1V62905	PASS 6277373
119	STL 010	TOYO	2006 TOYO HYPARADIAL S TOYO N34F9L60405	PASS 6277375
119	STL 011	CHAOYANG	2006 CHAOYANG LM516 LONG MARCH 1R4F1M130605	PASS 6277376
119	STL 012	SHIN HUNG RUBBER	2006 SHIN HUNG CONTI-MILESTONE CONTI. H6XKCLA1901	PASS 6277377
119	STL 013	PIRELLI GERMANY	2006 PIRELLI SCORPION SYNC PIRELLI 12EBF8XXAP2003	PASS 6277378
119	STL 014	PIRELLI GERMANY	2006 PIRELLI MEZ4 METZELER EBOOBRW4203	PASS 6277379
119	STL 015	CHENG SHIN RUBBER	2006 CHENG SHIN V BARRACUDA UYZ91305	PASS 6277380
119	STL 016	CONTINENTAL AG	2006 CONTINENTAL AG TKV-12Q CONTINENTAL CPIFA2AJ1701	PASS 6277381
119	STL 017	CHENG SHIN RUBBER	2006 CHENG SHIN MARQUIS CENG SHIN UYLS1405	PASS 6277382
119	STL 018	PIRELLI GERMANY	2006 PIRELLI MARATHON METZELER EBW1F9431105	PASS 6277383
119	STL 019	PIRELLI PNEUS S.A.	2006 PIRELLI LASERTEC METZELER XE7BF3094904	PASS 6277384
119	UTG 181	NEXEN TIRE CORP.	2006 NEXEN RADIAL N3000 8EUC1405	PASS 6277385
119	UTG 182	NEXEN TIRE CORP.	2006 NEXEN RADIAL N3000 8EUC1405	PASS 6277386
119	UTG 177	NANKUNG RUBBER TIRE CORP.	2006 NANKUNG S-665 SONAR WE9L1680805	PASS 6277387
119	SSS 001	PIRELLI PNEUS S.A.	2006 PIRELLI ROUTE MT 66 XEK276081505	PASS 6277393
119	SSS 002	PIRELLI GERMANY A.G.	2006 PIRELLI METZELER MEZ4B EBOVBRV4103	PASS 6277394
119	SSS 003	PIRELLI PNEUS S.A.	2006 PIRELLI SPORT DEMON XEEXD4272305	PASS 6277395
119	SSS 004	PIRELLI PNEUS S.A.	2006 PIRELLI ROUTE MT 66 XET8092105	PASS 6277396

REPORTS ACCEPTED DURING SEPTEMBER 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFG/ DISTRIB	MY BRAND/ TIRE_NAME/ID NUMBER	HSNO/ RESULT
119	SSS 005	PIRELLI GERMANY A.G.	2006 PIRELLI SCORPION SYNC EBPTE4794204	PASS 6277397
119	SSS 006	CHENG SHIN RUBBER IND. CO. LTD.	2006 CHENG SHIN HI-MAX UYES1905	PASS 6277398
119	SSS 007	CHENG SHIN RUBBER IND. CO. LTD.	2006 CHENG SHIN TIRE CS MARQUIS UYJS1205	PASS 6277399
119	SSS 008	PIRELLI PNEUS S.A.	2006 PIRELLI SPORT DEMON XEF8D4251805	PASS 6277400
119	SSS 009	TOYO TIRE & RUBBER CO. LTD.	2006 TOYO HYPARADIAL S N34F9LM2405	PASS 6277401
119	SSS 010	YOKOHAMA RUBBER CO. LTD.	2006 YOKOHAMA SUPERSTEEL TY517 FB3TUFV1405	PASS 6277402
119	SSS 011	YOKOHAMA RUBBER CO. LTD.	2006 YOKOHAMA SUPERSTEEL RY083A FB3TUCP0404	PASS 6277403
119	SSS 012	MICHELIN TYRE CO. LTD.	2006 MICHELIN XZE HJ3TA7MX2505	PASS 6277404
119	SSS 013	YOKOHAMA RUBBER CO. LTD.	2006 YOKOHAMA SUPERSTEEL RY 637 ST FB3TVDW1905	PASS 6277405
119	SSS 014	MICHELIN NORTH AMERICA CANADA	2006 MICHELIN X GREEN XDA2 M53TANCX1703	PASS 6277406
119	SSS 015	MICHELIN NORTH AMERICA CANADA	2006 MICHELIN XDN2 M53TAWLX4503	PASS 6277407
119	SSS 016	YOKOHAMA RUBBER CO. LTD.	2006 YOKOHAMA SUPERSTEEL TY577 FB3TVE22004	PASS 6277408
119	SSS 017	MT. VERNON OF GENERAL TIRE INC.	2006 YOKOHAMA SUPERSTEEL RY671 6B3T1UA2405	PASS 6277409
119	SSS 018	MICHELIN NORTH AMERICA CANADA	2006 MICHELIN XZA2 M53TB6YX1405	PASS 6277410

Note: The tire description usually includes an ID number. The tire ID number changes by production week and it is not a tire serial number. Tire ID numbers that are identical indicate that the tires were manufactured during the same week, not that they are the same tire.

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH SEPTEMBER 2006
(CI NUMBER SYSTEM EXAMPLE: "CI-208-051220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2005)**

NONE

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH SEPTEMBER 2006
(PE NUMBER SYSTEM EXAMPLE: "PE-208-051220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2005)

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-201-050325	General Motors Corp./2005 Buick Lactosse/Upper roof rail target (Ur2):1164 HIC<1000 HIC	CT
PE-208-050721	Volvo North America Corp./2005 Volvo S40/Data request/Passenger failed Nij	CT

PEs OPENED SINCE LAST REPORT

NONE

PEs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect